



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Out going

Inspection Report

Supervisor 14

Minerals Regulatory Program

Date of Report: 04/15/2008

Mine Name: Levan Henry

Operator Name: Sunroc

Permit number: M0230023

Inspection Date: 04/09/08

Time: 12:34 pm

Inspector(s): Leslie Heppler, Dan Smith

Other Participants: none

Mine Status: Active

Weather: 30-40 deg, starting to snow

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection: This was a routine annual inspection

Inspection Summary: Gate was torn off hinges. Stockpile was eroding (see photos). No equipment on site at the time of inspection. No active highwall is being mined. Several stockpiles of processed material are on site.

Conclusions and Recommendations: Bond expired 03/20/96. Operator has 30 days to escalate bond.

Inspector's Signature *Le Henry* **Date:** 04-15-08

Photos Taken 04-09-08



lah:pb

cc: Susan White, Lynn Kunzler
Tony Christofferson
Agency – Uinta National Forest / Fee